

TRIUMPH & LUCAS PART NUMBERS					
05-20 Starter Motor	Part No				
	Triumph	Lucas			
		1971	1972	1973	1987 Supersession
Starter motor	215111	25627E			
Starter motor	215111/2		25648E	25648E	
Pivot bolt		54240485			Not Serviced
Nut for pivot bolt		272549			Not Serviced
Pivot pin kit			54246454	54246454	54260461W10
Sundry parts kit	503721	271731			
Sundry parts kit	503721		54246438	54246438	
Bush - drive end	517467	54252054			TCB116
Bracket - drive end	519536	54243000			
Bracket kit - drive end			54245696		Not Serviced
Bracket kit - drive end				54249558	Obsolete
Thrust washer - drive end	519537	54250549			Not Serviced
Jump ring - drive end	519538	54250703			
Thrust collar - drive end	517469	54252863			TLB186
Bush	519534	54252075			Not Serviced
Drive	519533	54242102			Not Serviced
Drive plate, lever operating	517464	54259624			Not Serviced
Drive ring, bush retaining	517463	291013			
Pinion engaging lever	517461	54240960			Not Serviced
Drive kit			54246253		TNB144
Drive kit				54249034	TNB144
Drive kit					
Engaging lever kit			54246254		Not Serviced
Engaging lever kit				60600031	
Lever retention kit			54245340	54245340	Not Serviced
Solenoid - suitable for 215111	519535	76826			TOB162
Solenoid - suitable for 215111/2	520473		76878	76878	TOB159
Solenoid base assembly with spindle & contact plate		54643283			Obsolete
Solenoid plunger spring		54641483			Not Serviced
Solenoid end cover kit			54644303	54644303	TWB114
Armature	517473	54240322			Not Serviced
Armature kit	517473		54246259	54246259	THB101
Field coil set	517475	54240313			Obsolete
Field coil kit	517475		54246977	54246977	TEB126
Cover band	517454	54240319			Not Serviced
Cover band fixing screw	517455	127584			
Cover band fixing nut	517456	169160			
Bush - commutator end	509818	251477			TCB125
Fabric thrust washer - commutator end	519540	54140203			Not Serviced
Thrust washer - commutator end	519539	54140202			Not Serviced
Brush set	GSB103	255659			TAB127
Brush kit	GSB103		54246258	54246258	TAB124
Brush tension spring set	517458	54257221			
Bracket - commutator end	517457	54240300			Not Serviced
Bracket kit - commutator end			54245645	54245645	54266139
Bolt, through fixing	511596	256009			Not Serviced
Bolt, through fixing	511596		54246979	54246979	Not Serviced
Bush kit - drive & commutator ends			54246976	54246976	TCB116
Sealing kit			54246978	54246978	